

FIG. 2A




FIG. 2B




FIG. 2C




FIG. 2D




FIG. 2E




FIG. 2F




FIG. 3A




FIG. 3B




FIG. 4A




FIG. 4B




FIG. 5A




FIG. 5B




FIG. 6




FIG. 7A




FIG. 7B




FIG. 8A




FIG. 8B




FIG. 9

TITLE: PCB SAMPLER INVENTORS: IVANCIC et al. FILED: 03/31/2004

ATTORNEY DOCKET: 12691 15 / 20




FIG. 10






FIG. 11



TITLE: PCB SAMPLER
INVENTORS: IVANCIC et al.
FILED: 03/31/2004



TITLE: PCB SAMPLER INVENTORS: IVANCIC et al. FILED: 03/31/2004

ATTORNEY DOCKET: 12691 19 / 20

Relationship of Aroclor 1254 Equivalent Mass Vs Actual PPM Mass in Paint (two pain types, epoxy and antifouling polymer)




FIG. 14




FIG. 15